



## Condition Based Servicing (CBS).

You will visit our workshop only when your BMW tells you.



### Engine oil

- Engine oil and oil filter changed
- Check handbrake

BMW 1 Series E87 (116i): Rs 3,389  
BMW 3 Series E90 (316i, 320i): Rs 3,453  
BMW 5 Series E60 (520i, 525i, 530i): Rs 4,098  
BMW 5 Series E60 (523i): Rs 4,029  
BMW 5 Series E 60 (525d, 530d): Rs 4,932  
BMW 5 Series F10 (523i, 528i, 535i): Rs 4,103  
BMW X1 E84 (18d, 20d): Rs 3,941  
BMW X3 F25 (28i): Rs 4,029  
BMW X3 F25 (20d): Rs 3,998  
BMW X3 F25 (30d): Rs 4,328  
BMW X5 E70 (30i), X6 E71(35i): Rs 4,339  
BMW X5 E70 (30d), X6 E71(30d): Rs 4,926



### Front brakes

- Change brake pads
- Change wear sensor
- Clean caliper cavities
- Replace discs if worn to minimum levels

BMW 1 Series E87 (116i): Rs 10,304  
BMW 3 Series E90 (316i, 320i): Rs 11,684  
BMW 5 Series E60 (520i, 523i, 525i, 530i, 525d, 530d): Rs 12,834  
BMW 5 Series F10 (523i, 528i): Rs 11,322  
BMW 5 Series F10 (535i): Rs 16,382  
BMW X1 E84 (18d, 20d): Rs 10,120  
BMW X3 F25 (28i, 30d): Rs 12,535  
BMW X3 F25 (20d): Rs 12,075  
BMW X5 E70(30i, 30d), X6 E71 (35i, 30d): Rs 13,984



### Rear brakes

- Change brake pads
- Change wear sensor
- Clean caliper cavities
- Check condition, brake lining thickness and function of handbrake
- Replace components if necessary

BMW 1 Series E87 (116i): Rs 10,580  
BMW 3 Series E90 (316i, 320i): Rs 10,580  
BMW 5 Series E60 (520i, 523i, 525i, 530i, 525d, 530d): Rs 11,500  
BMW 5 Series F10 (523i, 528i, 535i): Rs 11,000  
BMW X1 E84 (18d, 20d): Rs 10,396  
BMW X3 F25 (20d, 28i,30d): Rs 11,247  
BMW X5 E70 (30i, 30d), X6 E71 (35i, 30d): Rs 13,651



### Spark plugs

- Replace spark plugs to ensure optimum performance, fuel economy and low emissions

BMW 1 Series E87 (116i): Rs 4,347  
BMW 3 Series E90 (316i): Rs 3,979  
BMW 3 Series E90 (320i): Rs 6,095  
BMW 5 Series E60 (520i, 523i, 525i, 530i): Rs 9,223  
BMW 5 Series F10 (523i, 528i): Rs 5,158  
BMW 5 Series F10 (535i): Rs 8,631  
BMW X3 F25 (28i): Rs 5,290  
BMW X5 E70 (30i): Rs 8,303  
BMW X6 E71 (35i): Rs 8,648



### Brake fluid

- Replace brake fluid every 2 years

BMW 1 Series E87 (116i): Rs 2,622  
BMW 3 Series E90 (316i, 320i): Rs 2,622  
BMW 5 Series E60 (520i, 523i, 525i, 530i, 525d, 530d): Rs 3,358  
BMW 5 Series F10 (523i, 535i): Rs 2,145  
BMW 5 Series F10 (528i): Rs 2,628  
BMW X1 E84 (18d, 20d): Rs 2,438  
BMW X3 F25 (28i, 30d): Rs 2,254  
BMW X3 F25 (20d): Rs 2,622  
BMW X5 E70 (30i, 30d), X6 E71 (35i, 30d): Rs 2,438



### Micro filters (Air conditioning filter)

- Micro filters trap 80% of pollen and traffic fumes maintaining a pleasant passenger environment

BMW 1 Series E87 (116i): Rs 3,979  
BMW 3 Series E90 (316i, 320i): Rs 3,979  
BMW 5 Series E60 (520i, 523i, 525i, 530i, 525d, 530d): Rs 7,383  
BMW 5 Series F10 (523i, 528i, 535i): Rs 7,481  
BMW X1 E84 (18d, 20d): Rs 3,979  
BMW X3 F25 (20d, 28i, 30d): Rs 4,899  
BMW X5 E70 (30i, 30d), X6 E71 (35i, 30d): Rs 7,671



### Vehicle check

- Check condition of vehicle systems including:
  - Exterior panelling and underbody for corrosion and damage
  - Tyres, steering and shock absorbers
  - Electrical systems including battery, headlights and indication field lighting
  - Safety including brakes and seat belts
  - Coolant and fluid levels

BMW 1 Series E87 (116i): Rs 2,737  
BMW 3 Series E90 (316i, 320i): Rs 2,737  
BMW 5 Series E60 (520i, 523i, 525i, 530i, 525d, 530d): Rs 3,105  
BMW 5 Series F10 (523i, 528i, 535i): Rs 2,375  
BMW X1 E84 (18d, 20d): Rs 2,369  
BMW X3 F25 (20d, 28i, 30d): Rs 2,369  
BMW X5 E70 (30i, 30d), X6 E71 (35i, 30d): Rs 3,105

### Validity: 30th June 2012

Prix incluant : Main d'oeuvre + Matériaux + TVA  
Taux de change : MUR 40.56 / € 1.00  
Notre offre est établie par rapport au taux de change susmentionné et donc soumise à toute fluctuation de plus de 10%

### Leal & Co. Ltd

Motorway M1, Pailles  
Tel: 207 2454, Fax: 286 5541  
Email: service@leal.lealgroup.com